

CLEAN AS A WHISTLE !



Plumber Lee Beckett, was astounded at the lack of limescale.

He will now recommend the X8 to all of his clients.

Report and pictures courtesy of Richard Ranson

Richard Ranson lives in a very “hard” water area in Surrey. He therefore had a water-conditioning magnet fitted to the cold water supply to his hot water cylinder some years ago.

He recently had the hot water cylinder in his house replaced, while re-fitting his bathroom.

The plumber mentioned how light the cylinder felt compared to the weight of those he usually replaced, and Richard asked him to cut it open so they could have a look at the coil.

As you can see, there is not a trace of limescale, other than a few remaining pieces of scale laying in the bottom of the cylinder.

(Government statistics show that just ¼” (6mm) of limescale on the heating coil of a hot water cylinder can increase the cost of heating water by 40%.)



X8 fitted to the cold water supply to the cylinder